



**World Electric
Maintenance Code Summary
Mississippi Valley Region**

Distribution

Circuit: 66355 - Schuyler

Maint Code	Count	Qty	Description	Target Time (Hrs)	← Cost →		← Extended →			Total Cost
					Labor	Material / Transportation	Time (Hrs)	Labor	Material / Transportation	
101	2		Street Light - Glass broken/damaged	0.48	\$19	\$26				
104	1		Street Light - Light on day	0.48	\$19	\$14				
112	5		Pole - Excess checking	11.70	\$452	\$609				
115	1		Pole - Riser guard required	0.48	\$19	\$49				
117	1		Pole - Leaning pole	5.85	\$226	\$248				
118	2		Pole - Stencil required/correction req.	0.08	\$3	\$4				
130	1	1	Insulator - Broken/Cracked/Flashed	1.47	\$57	\$71	1	\$57	\$71	\$128
132	18	123	Insulator - I-7 aluminum caps	2.20	\$85	\$71	271	\$10,425	\$8,740	\$19,166
144	1		Primary - Poor insulation	0.48	\$19	\$74				
201	2	2	Arrestor - Blown arrestors	1.95	\$75	\$100	4	\$151	\$200	\$351
220	38	38	Guy - Guy Wire marker	0.08	\$3	\$10	3	\$119	\$389	\$508
222	3		Guy - Excessive slack in guy	1.95	\$75	\$91				
223	1		Guy - Broken guy wire	1.95	\$75	\$91				
230	2		Secondary - Poor insulation	2.43	\$94	\$203				
231	4		Secondary - In trees	4.38	\$170	\$49				
232	1		Secondary - Improper sag	1.95	\$75	\$66				
234	8		Secondary - Floating	0.98	\$38	\$16				
240	1	1	Service - Ins. loose from house	1.95	\$75	\$66	2	\$75	\$66	\$141
241	3	3	Service - In trees	4.38	\$170	\$49	13	\$509	\$148	\$657
242	1	1	Service - Poor insulation	1.95	\$75	\$85	2	\$75	\$85	\$161
	<u>96</u>		Occurrences for circuit 66355 - Schuyler			Totals	<u>296</u>	<u>\$11,411</u>	<u>\$9,699</u>	<u>\$21,112</u>
	<u>96</u>		Occurrences for Mississippi Valley Region			Totals	<u>296</u>	<u>\$11,411</u>	<u>\$9,699</u>	<u>\$21,112</u>